



# Additional Information

## Pressure and suction pressure with air and pumps in serial connection



All values are approximate and no guarantee of specific technical properties.

Changes in the course of technical progress are possible without notice.

#### Contact Data:

Bartels Mikrotechnik GmbH  
Konrad-Adenauer-Allee 11  
44263 Dortmund Germany  
[www.bartels-mikrotechnik.de](http://www.bartels-mikrotechnik.de)  
[info@bartels-mikrotechnik.de](mailto:info@bartels-mikrotechnik.de)  
Tel: +49-231-47730-500  
Fax: +49-231-47730-501

#### Visit our Website

[www.bartels-mikrotechnik.de/downloads](http://www.bartels-mikrotechnik.de/downloads)

for further information on applications.

Tutorials and helpful answers to frequently asked questions can be found in our FAQ

[www.bartels-mikrotechnik.de/en/faq-english/](http://www.bartels-mikrotechnik.de/en/faq-english/)

or on our YouTube channel

<https://www.youtube.com/user/BartelsMikrotechnik>

Find us on Social Media:

